



Verizon  
600 Hidden Ridge  
Irving, TX 75015-2092

**PUBLIC NOTICE OF NETWORK CHANGE UNDER RULE 51.329(A)**

April 19, 2012

**Carrier:** Verizon Virginia LLC  
703 East Grace Street, Richmond, VA 23219

**Contact:** For additional information on these planned network changes, please contact:

Peter J. D'Amico  
Sr. Consultant – Product Management/Product Development  
416 7<sup>th</sup> Ave., 19<sup>th</sup> Floor  
Pittsburgh, PA 15219  
peter.j.damico@one.verizon.com  
412-633-8424

**Implementation Date:** November 1, 2012 (or later)

**STP Locations Impacted by this Network Disclosure:**

LATA	Location	CLLI	Point Code	Address
250	Church St.	LYBGVACH77W	246-240-000	700-706 Church St., Lynchburg VA 24504
250	Timberlake	LYBGVATM77W	246-241-000	7216 Timberlake Rd., Lynchburg VA 24502
244	Roanoke	RONKVALK77W	246-220-000	225 Franklin Rd., Roanoke, VA 24011
244	Salem	SALMVASA77W	246-221-000	10 S Market St., Salem VA 24157

**Description of the Planned Network Changes:**

The Signaling System 7 (SS7) links originating from the Verizon Virginia LLC (VZ VA) end offices in the 250 Lynchburg LATA listed below will be rehomed from the VZ VA Church St. (LYBGVACH77W) Signal Transfer Point (STP) and the VZ VA Timberlake (LYBGVATM77W) STP to the VZ VA Roanoke (RONKVALK77W) STP and the VZ VA Salem (SALMVASA77W) STP in the 244 Roanoke LATA.

After completion of the network changes, SS7 services currently provided by the VZ VA Church St. and VZ VA Timberlake STPs will be provided via the VZ VA Roanoke and VZ VA Salem STPs.

**Verizon VA End Offices LATA 250 Subject to this Network Disclosure:**

Office Name	CLLI	Link Type	Location
Franklin Pike	DAVLVAFPDS0	A	904 Franklin Pike, Danville VA 24541
Danville	DAVLVADA03T	A	730 Main St., Danville VA 24541
Timberlake	LYBGVATMDS0	A	7216 Timberlake Rd., Lynchburg VA 24502
New London Rd.	LYBGVANLDS0	A	3357 Thomas Jefferson Rd., Bedford VA 24551
Clearview	LYBGVACVDS0	A	100 Clearview Dr., Campbell VA 24504
Church St.	LYBGVACH03T	A	700-706 Church St., Lynchburg VA 24504

**Description of Reasonably Foreseeable Impact of the Planned Changes:**

SS7 service providers will need to alter their SS7 transport, OffNet services arrangements (services obtained from third parties) and/or Gateway services in order to access or continue serving customers in the 250 Lynchburg LATA.