



6929 N. Lakewood Avenue  
Tulsa, OK 74117

**SHORT TERM PUBLIC NOTICE OF NETWORK CHANGE UNDER RULE 51.333(a)**

November 14, 2016

**Carrier:** Verizon North LLC, 1717 Arch Street, Philadelphia, PA 19103

**Contact:** For additional information on these planned network changes, please contact:

Lisa Thompson  
Global Engineering and System Performance  
Verizon Wireline Network Operations  
13100 Columbia Pike, 05 Floor, Room 505  
Silver Spring, MD 20904  
443-862-0212

Andrea Karcher  
Senior Manager – Global Engineering and System Performance  
Verizon Wireline Network Operations  
31 S. Beaver St, 05 Floor, Room 5W5A,  
York, PA 17401  
717-771-5222

**Implementation Date:** On or after February 24, 2017

**Planned Network Change(s) will occur at the following locations in Pennsylvania:**

Verizon Central Office	Address	CLLI
LOYALSOCK MAIN, PA	4218 RT 87 HWY, Loyalsock, PA 17754	LYLCPAXLDS0
SELINSGROVE, PA	21 S. Market Street, Selinsgrove, PA 17870	SLGVPAXSDS0

This notice may also be viewed at <http://www.verizon.com/about/terms-conditions/network-disclosures>

**Description of the Planned Network Change(s):**

The Verizon Loyalsock Main DCO (Digital Central Office) switch (LYLCPAXLDS0) located at 4218 RT 87 HWY, Loyalsock, PA 17754, will be retired and removed from the network after all traffic served by this switch is migrated to the alternative switch described below. All traffic currently handled by the Loyalsock Main DCO switch (LYLCPAXLDS0) will be migrated to the Selinsgrove DMS (Digital Multiplex System) 100 switch (SLGVPAXSDS0) located at 21 S. Market Street, Selinsgrove, PA 17870. All traffic will be migrated to the Selinsgrove DMS 100 switch

(SLGVPAXSDS0) including, but not limited to, Inter-LATA (ACCESS/FG-B-D/CLEC/IXC), wireless, and paging traffic.

**Description of Reasonably Foreseeable Impact(s) of the Planned Change(s):**

Competitive local exchange carriers (CLECs), interexchange carriers (IXCs, IECs), wireless carriers, and paging carriers, will need to secure new trunk groups built to the Selinsgrove DMS 100 switch (SLGVPAXSDS0) or have existing trunk groups to that switch augmented. Carriers that are code holders for access connectivity in the Loyalsock Main DCO switch (LYLCPAXLDS0) will be required to reposition the codes to the Selinsgrove DMS 100 switch (SLGVPAXSDS0).

All ASRs for the Selinsgrove DMS 100 switch (SLGVPAXSDS0) must be received no later than February 4, 2017 in order to provide sufficient time to migrate the traffic described above. All traffic must be moved by February 18, 2017. All ASRs for the Selinsgrove DMS 100 switch (SLGVPAXSDS0) must carry the project code of LYLCPAXLRS0.